

Accessories



Filter for PCA

see PCA Spare Parts

Fluoride, Colorimeter Reagents

see Section V

Fluoride Standard Solutions

see Section F

Formaldehyde, Test Kit Reagents

see Section V

Fuse

HI 70490P	400 mA, 5 x 20 mm fuse (10 pcs)
HI 740136P	1 A, 5 x 20 mm fuse (10 pcs)
HI 740137	1 A, 5 x 20 mm fuse (6 pcs)
HI 740138P	2 A, 5 x 20 mm fuse (10 pcs)
HI 740139	2 A, 5 x 20 mm fuse (6 pcs)
HI 740214	5 A, 5 x 20 mm fuse (1 pcs)
HI 740215	5 A, 5 x 20 mm fuse (6 pcs)

G

Glycol, Test Kit Reagents

see Section V

H

Hardness, Colorimeter Reagents

see Section V

Hardness, Test Kit Reagents

see Section V

HI 83215 Accessories

Complete accessory kit for preparation of samples to be analyzed (nutrients for agriculture) with the HI 83215 photometer.

HI 740223	Plastic beaker (170 mL)
HI 740224	Plastic beaker (170 mL, 12 pcs)
HI 740225	Syringe (60 mL)
HI 740226	Pipette (5 mL)
HI 740227	Filter
HI 740228	Filter (25 pcs)
HI 740229	Polypropylene cylinder (100 mL)
HI 740230	Demineralized bottle (230 mL)
HI 93703-54	Resin (100 g)
HI 93703-55	Active carbon (for 100 tests)
HI 83215K	Rugged carrying case containing the following kit for HI 83215: 100 mL and 170 mL beakers, 5 mL and 60 mL syringes, filter holder and 25 filters, 100 mL cylinder, demineralizer bottle, 1.5 mL spoon, 2 pipettes and active carbon for 50 tests

