


Accessories



Probe, Temperature, Thermistor and Thermocouple

see Section P

Pump Spare Parts

List of necessary spare parts for operation and maintenance of dosing pumps.

HI 721003	Glass ball with O-ring (10 pcs each)
HI 721004	Injection valve assembly
HI 721005	Foot valve assembly
HI 721006	Spring (4 pcs)
HI 721008	Ceramic weight (4 pcs)
HI 720029	LDPE hose, 3 m (9.9')
HI 720030	LDPE hose, 10 m (33')
HI 720031	LDPE hose, 50 m (165')
HI 720032	LDPE hose, 100 m (333')
HI 721101	Pumphead, O-ring, screws (6 pcs) and washers (6 pcs)
HI 721102	Discharge valve assembly
HI 721103	Suction valve assembly
HI 721108	PVDF nut (25 pcs)
HI 740156	Valve seat (3 pcs)

R

Rack, Test Tube Cooling

HI 740216	Test tube cooling rack (25 holes)
-----------	-----------------------------------

Reagents for Chemical Test Kits

see Section V

Reagents for PCA Series

see PCA Spare Parts

Reagents for Photometers

see Section V

RH Calibration Chamber

These portable chambers allow you to easily calibrate your hygrometers. They measure 190 x 115 x 110 mm (7.5 x 4.5 x 4.3"), and are supplied complete with O-ring and precalibrated, ready-to-use saturated salts.

The HI 7101 model is designed for use with HI 8564, HI 9064, HI 9065, HI 9161, HI 9261 and HI 91610 instruments, while the HI 7102 is for use with the HI 93640 and HI 8666 hygrometers.

HI 7101	Calibration chamber for RH probes with sintered cap
HI 7102	Calibration chamber for RH probes without sintered cap

RH Calibration Salt

LiCl calibration salt for HI 7101 & HI 7102 calibration chambers (low RH).

HI 7111/P	LiCl calibration salt, 15 g bottle (6 pcs)
-----------	--

NaCl calibration salt for HI 7101 & HI 7102 calibration chambers (high RH).

HI 7121/P	NaCl calibration salt, 33 g bottle (6 pcs)
-----------	--

