

Accessories



HI 70456	0.1 N NaOH solution (1 L)
HI 70457	1 N NaOH solution (1 L)
HI 70458	0.01 M H ₂ SO ₄ solution (1 L)
HI 70459	0.05 M H ₂ SO ₄ solution (1 L)
HI 70462	0.01 N HCl solution (1 L)
HI 70463	0.1 N HCl solution (1 L)
HI 70464	1 N HCl solution (1 L)
HI 70465	Reagent for hydrogen peroxide titration (30 mL)
HI 70466	0.00564 N phenylarsine dioxide (PAO) standard solution (500 mL)
HI 70467	Acetate buffer at pH 4 (200 mL)
HI 70468	Potassium iodide powder (for 100 tests)
HI 70469	0.00188 N iodine standard solution (4 x 250 mL)
HI 70470	0.00564 N diphenylarsine oxide (PAO) standard solution (500 mL)
HI 70471	0.000564N phenylarsine oxide (PAO) standard solution (500 mL)
HI 70472	Phosphate buffer at pH 7 (200 mL)

Tool for Calibration

To perform manual calibration of the HI 99104 pH tester.
HI 740091P Calibration tool for HI 99104 (20 pcs)

Tool for Replacing Probe

Used for removing the probe cartridge of HI 98120, HI 98121, HI 98127, HI 98128, HI 98129, HI 98130, HI 98311 and HI 98312 testers.
HI 73128P Probe removal tool (10 pcs)

Transformer

see Power Adapter

Transmitter, Infrared, for PC Connection

Infrared interfaces to be used with portable meters. Simply place the unit on the cradle and the data will be transmitted to the PC through the RS232 serial port.

HI 9200/9	Infrared transmitter with 9-pin serial connector
HI 9200/25	Infrared transmitter with 25 pin serial connector

Infrared interfaces to be used with temperature dataloggers.

HI 90140	Infrared transmitter for HI 140 series
HI 141001	Infrared transmitter for HI 141 series

V

Vessel for Water Test

Plastic vessel to collect sample being measured with Water Test.

HI 740088	Vessel for Water Test
-----------	-----------------------

Vial - see also Cuvet

To be used with HI 3835 salinity test kit, to perform the reaction during titration.
HI 740196P Plastic vial for HI 3835 (20 pcs)

